

Précautions de manipulation et de stockage des produits SAMR Métal Rouge SAS

Manipulation

Lors de la manipulation, aucun choc ne doit avoir lieu.

Lors du désemballage, ne pas utiliser d'outil tranchant, taillant qui pourrait impacter les surfaces fragiles des produits.

Les arêtes vives doivent être maintenues protégées et les pièces doivent rester calées de manière à empêcher tout mouvement de celles-ci.

Stockage

Toute variation importante de température doit être évitée.

Les pièces doivent être stockées dans un lieu sec (entre 15°C et 35°C).

Le taux d'humidité maximum doit être de 60%.

Precautions of manipulations and storage of products SAMR Métal Rouge SAS

Manipulation

During the manipulation, no shock has to take place.

During the unpacking, do not use cutting, cutting tool which could impact on the fragile surfaces of products.

All the edges must be protected and parts must be propped up so as to prevent any movement of these.

Storage

Any important variation of temperature must be avoided.

Parts must be stored in a dry place (between 15°C and 35°C).

The maximum rate of humidity must be of 60%.

